RCUD JAN12'07 DIL CONS. DIV.

DIST. 3



NEW MEXICO ENERGY, MINERALS and NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178
FAX: (505) 334-6170

www.emnrd.state.nm.us/ocd/District 3/district3.htm

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

Date of Test 11-06 0	perator_	70 Fauc STHC API #30-0 SF	04924925
Property Name Campbell Com Well 1			,
Well Status (Shut-In or Producing) Tubi			,
OPEN BRADENHEAD AND INTERMED	DIATE TO	O ATMOSPHERE INDIVIDUALLY FOR 1	5 MINUTES EACH
PRESSURES: TIME BRADENHEAD INTERMEDIATE	CASING	BRADENHEAD FLOWED	INTERMEDIATE FLOWED
5 minutes		Steady Flow	
10 minutes		Surges	
15 minutes		Down to Nothing	
20 minutes		Nothing	
25 minutes		Gas	
30 minutes		Gas & Water	
		Water	
If bradenhead flowed water, check all of the descriptions that apply below:			
CLEAR FRESH SALTY SULFUR BLACK			
5 MINUTE SHUT-IN BRADENHEAD INTERMEDIATE			
REMARKS:			
12			
By To hands		Witness	
(Position)			
E-mail address			