RCVO JANIZVI DIL COMO. DIV. DIST. 3



4 John Aldress

NEW MEXICO ENERGY, MINERALS and NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178
FAX: (505) 334-6170

www.emnrd.state.nm.us/ocd/District 3/district3.htm

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

Date of Test 6 - 26 - 06	Operator Ch	elron	API #30-0 <u>5 Fo</u>	90692/ 29366
Property Name Rincon	<u>Pc_</u> Well No. <u>99</u> I	Location: Unit	Section 22 Townsh	nip <u>27</u> Range <u>6 w</u>
Well Status (Shut-In or Produc	ing) Tubing 22 Inter	mediate Ca	asing 52 Bradenh	ead <u>o</u>
OPEN BRADENHEAD AND	INTERMEDIATE TO AT	MOSPHERE IND	IVIDUALLY FOR 15	MINUTES EACH
PRESSU TIME BRADENHEAD INTER			BRADENHEAD FLOWED	INTERMEDIATE FLOWED
5 minutes		Steady Flow		
10 minutes				
15 minutes		Down to Nothi	ng	
20 minutes				
25 minutes		Gas		
30 minutes		Gas & Water		
If bradenhead flowed water, check a	ll of the descriptions that ap	oply below:		
CLEAR FRESH	SALTY SULI	FUR BLACE	K	
5 MINUTE SHUT-IN BRADENHEAD INTERMEDIATE				
REMARKS:				
- in/m				
. And the second section of the second section of the second section of the second section of the second section secti		tage for the second		
			and the second s	
By Loo Danuls	Witne			
(Pesition)				