RCVD JAN12'0? GIL CONS. DIV. DIST. 3



NEW MEXICO ENERGY, MINERALS and NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION AZTEC DISTRICT OFFICE 1000 RIO BRAZOS ROAD AZTEC NM 87410 (505) 334-6178 FAX: (505) 334-6170

www.emnrd.state.nm.us/ocd/District 3/district3.htm

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

	4506482
Date of Test 6 - 2 - 0 6 Oper	ator Four STAC API #30-0 5F 078357
Property Name Marchail Centle Well No.	1K Location: Unit Section 14 Township > Range 7W
Well Status (Shut-In or Producing) Tubing	297 Intermediate Casing 351 Bradenhead
OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH	
PRESSURES: TIME BRADENHEAD INTERMEDIATE CA	SING BRADENHEAD INTERMEDIATE FLOWED FLOWED
5 minutes	Steady Flow
10 minutes	Surges
15 minutes	Down to Nothing
20 minutes	Nothing
25 minutes	Gas
30 minutes	Gas & Water
	Water
If bradenhead flowed water, check all of the descriptions that apply below:	
CLEAR FRESH SALTY SULFUR BLACK	
5 MINUTE SHUT-IN BRADENHEAD	INTERMEDIATE
REMARKS:	
1.00	
By teo Wanuly	Witness
(Position)	
E-mail address	<u>.</u>