

## NEW MEXICO ENERGY, MINERALS and ATURAL RESOURCES DEPARTMENT BRADENHEAD TEST REPORT NATURAL RESOURCES

**OIL CONSERVATION DIVISION AZTEC DISTRICT OFFICE** 1000 RIO BRAZOS ROAD **AZTEC NM 87410** (505) 334-6178 FAX: (505) 334-6170 mid.state.nm.us/ocd/District 3/district3.htm

(Submit 2 copies to above address)

Date of Test 12 22 06 Operator	HUNTINGTON Energy API #30-0 39-2353)
Property Name Clu Well No. 131R Location: Unit Section 9 Township 40 Range 60	
Well Status (Shut-In on Producing) Tubing 40 Intermediate Casing 40 Bradenhead ()	
OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH	
PRESSURES: TIME BRADENHEAD INTERMEDIATE CASING	BRADENHEAD INTERMEDIATE FLOWED FLOWED
5 minutes O	Steady Flow
10 minutes_	Surges
15 minutes	Down to Nothing
20 minutes	Nothing
25 minutes	Gas
30 minutes	Gas & Water
	Water
If bradenhead flowed water, check all of the descriptions that apply below:	
CLEAR FRESH SALTY SULFUR BLACK	
5 MINUTE SHUT-IN BRADENHEAD O INTERMEDIATE	
REMARKS:	
NO pressure, NO Flow	
By Dai Moraler	Witness
Leace operator (Position)	
E-mail address	