



NEW MEXICO ENERGY, MINERALS and NATURAL RESOURCES DEPARTMENT

RCUD MAR 23 '07
OIL CONS. DIV.

DIST. 3

MECHANICAL INTEGRITY TEST REPORT

(TA OR UIC)

Date of Test 3/23/07 Operator Burlington API # 30-0 45-28563

Property Name SAN JUAN 32-9 SWD Well # 5 Location: Unit A Sec 18 Twn 31 Rge 9

Land Type:

State _____
Federal ☒ _____
Private _____
Indian _____

Well Type:

Water Injection ☒ _____
Salt Water Disposal _____
Gas Injection _____
Producing Oil/Gas _____
Pressure observation _____

Temporarily Abandoned Well (Y/N) (N) TA Expires: 3/23/2012 ^{5 years}

Casing Pres. _____ Tbg. SI Pres. _____ Max. Inj. Pres. _____
Bradenhead Pres. 0 Tbg. Inj. Pres. _____
Tubing Pres. 120
Int. Casing Pres. 0

Pressured annulus up to 480 psi. for 30 mins. Test passed ~~failed~~

REMARKS:

Good test run

PACKER at 8197.


Ref - 8253 - 9205

By [Signature]
(Operator Representative)

Witness [Signature]
(NMOCD)

(Position)

Revised 02-11-02



GRAPHIC CONTROLS CORPORATION
BUFFALO, NEW YORK

CHART NO. MC MP-3000-150F 75DIV
MIT *Packet-8197*

METER _____ CHART PUT ON _____ M TAKEN OFF _____ M

LOCATION *Burlington*
REMARKS *S.J. 32-9 SWD #5*
30-045-28563
3/23/2007

Handwritten notes and signatures in the upper right quadrant of the chart.

Handwritten signature in the lower right quadrant of the chart.

PRINTED IN U.S.A.