SWA

UNITED STATES DEPARTMENT OF THE INTERIOR **BUREAU OF LAND MANAGEMENT**

OIL CONS. DIV. DIST. 3

	Sundry Notices and Reports on Wells	7 APR -5	M 2: 24
1.	Type of Well GAS	RED 5 1VE 91.11 210 FAPY 6.	Lease Number NMSF-080669 If Indian, All. or Tribe Name
2.	Name of Operator	7.	Unit Agreement Name
	BURLINGTON RESCURCES OIL & GAS COMPANY LP		San Juan 27-4 Unit
3.	Address & Phone No. of Operator	8.	Well Name & Number
	PO Box 4289, Farmington, NM 87499 (505) 326-9700	9.	San Juan 27-4 Unit #45 API Well No.
4.	Location of Well, Footage, Sec., T, R, M		30-039-26529
	Sec., TN, RW, NMPM	10.	Field and Pool
	Unit I (NESE) 2240' FSL & 350' FEL, Sec. 19, T27N, R4W NMPM	Bland 11.	co Mesaverde/ Basin Dakota County and State
		11.	Rio Arriba Co., NM
	Type of Submission Notice of Intent Abandonment Recompletion X Subsequent Report Final Abandonment Altering Casing Change of Plans New Construction Non-Routine Fracturing Casing Repair Water Shut off Conversion to Injection	X Other	Tubing Repair
3/2 @ 15 Ta cle 62	27/07 MIRU Drake #22. Kill tbg w/10bbls 2% KCL H2O. ND tree. NU 6300'. TOOH w/2 3/8" tbg. TIH w/bailer. Tag fill @ 6200'. C/O w/bai 'fill @ 6235'. C/O from 6180' to 6230'. TIH w/3 7/8" bit. RU swivel. It g fill @ 6180'. RU swivel. Break circulation. C/O from 6180' to 6300' can. RD swivel. TIH w/199jts 2 3/8" tbg set @ 6183'. Blow w/air mist. 40'. RU swivel. C/O to PBTD. RD swivel. Load hole w/2% KCL. PT the U tree. Pump check, ok. Unload hole w/airmist. RD MO 4/2/07.	ler from 620 Break circula (PBTD) w/a Circulate cle	0'-6250'. Tag w/ ation. RD swivel. ir mist. Circulate an. Tag fill @
Sig	is space for Federal or State Office use) Amanda Sanchez	Title <u>Regulator</u>	y Tech Date 4/5/07
CC	PROVED BY		
	In the States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.		APR 0 6 2007