



NEW MEXICO ENERGY, MINERALS and NATURAL RESOURCES DEPARTMENT

MECHANICAL INTEGRITY TEST REPORT

(TA OR UIC)

Date of Test 4-19-07 Operator Dugan Rod. API # 30-0 45-33865

Property Name Franklin SW Well # 1 Location: Unit C Sec 30 Twn 24 Rge 10

Land Type:

State _____
Federal _____
Private _____
Indian _____

Well Type:

Water Injection _____
Salt Water Disposal ☒
Gas Injection _____
Producing Oil/Gas _____
Pressure observation _____

Temporarily Abandoned Well (Y/N): (Y)

TA Expires: _____

Casing Pres. 0
Bradenhead Pres. 0
Tubing Pres. 0
Int. Casing Pres. N/A

Tbg. SI Pres. _____
Tbg. Inj. Pres. _____

Max. Inj. Pres. _____

RCVD APR 19 '07

OIL CONS. DIV.

Pressured annulus up to 420 psi. for 30 mins. Test passed/failed

DIST. 3

REMARKS:

Packer Set at 6623
top of pack 6684

By Doug Anderson
(Operator Representative)

Witness Monica Treckling
(NMOCD)

Super Disol
(Position)

Revised 02-11-02

FRIDAY
12 3

6 9 12 3 6

SATURDAY
12 3 9

6 9 12 3 6

SUNDAY
12 3 9

6 9 12 3 6

MONDAY
12 3 9

6 9 12 3 6

TUESDAY
12 3 9

6 9 12 3 6

WEDNESDAY
12 3 9

6 9 12 3 6

THURSDAY
12 3 9

6 9 12 3 6

RCVD APR 1907

OIL CONS. DIV.

DIST. 3

GRAPHIC CONTROLS CORPORATION
BUFFALO, N.Y.
CHART NO. MC MP-500-S
44907
30-045-35865
C30-2410
TAKEN OFF
LOCATION IN MARKS
Frazdes WD#1
Dugan Rd.

CHART PUT ON
METER