submitted in lieu of Form 3160-5

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

	Sundry Notices and Reports on Wells	2007	MAY -3	PM 4: 08
1.	Type of Well GAS		RECEÍVA BLA O FARMITIS	Lease Number NMSF-078120A If Indian, All. or Tribe Name
2.	Name of Operator BURLINGTON	RECEIVED	7.	Unit Agreement Name
	RESCURCES OIL & GAS COMPANY LP	MAY 2007	8.	Well Name & Numbe
3.	Address & Phone No. of Operator PO Box 4289, Farmington, NM 87499 (505) 326-9700	CONS. DIV. DIST 3	9.	Federal G 1P API Weli No.
4.	Location of Well, Footage, Sec., T, R, M	E \$2527.129	10	30-045-33912
	Sec., TN, RW, NMPM		10	. Field and Pool Blanco MV/Basin Dako
	Unit E (SWNW) 2415' FNL & 1050' FWL, Sec. 35, T31N, R12W NMPM		11.	
	Casing Repair Water Shut of Altering Casing Conversion Describe Proposed or Completed Operations 3/07 RU BWWC. Ran CBL/GR/CCL from wireline PBTD 6905' to	to Injection	3340'. 7" sh	oe @ 4143'. RD BWWC.
2/2	2/07 PT 4 ½" casing to 4100 #/15min- OK.			
14	. I hereby certify that the foregoing is true and correct.	 		
Sig	aned July William Tracey N. Monroe	Title Regulatory	Technician	Date <u>5/3/07</u>
AP CC Title	nis space for Federal or State Office use) PROVED BY	cy of	•	_ Date
			LCCEF	TED FOR FEDORATION
				MAY 0 4 2007 MOTON FED OFFICE

NMOCD

