

NEW MEXICO ENERGY, MINERALS  
& NATURAL RESOURCES DEPARTMENT

Oil Conservation Division  
Aztec District Office  
1000 Rio Brazos Road  
Aztec, NM 87410  
(505)334-6178 FAX:(505)334-6170

<http://emnr.state.nm.us/ocd/District/III/3district.htm>

**BRADENHEAD TEST REPORT**  
(Submit 1 copy to above address)

RCVD MAY18'07  
OIL CONS. DIV.  
DIST. 3

Date of Test 5-9-07 Operator Dugan Production Corp. API # 30-039-20186  
Property Name Nordhaus Well No. 1 Location: Unit H Section 18 Township 25N Range 7W  
Well Status(Shut-In or Producing) Initial PSI: Tubing 90 Intermediate N/A Casing 90 Bradenhead 9

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

PRESSURE						FLOW CHARACTERISTICS		
	Bradenhead			Interm				
TIME	BH	Int	Csg	Int	Csg		BRADENHEAD	INTERMEDIATE
5 mintues	8		90			Steady Flow		
10 minutes	8		90			Surges		
15 minutes	8		90			Down to Nothing		
20 minutes						Nothing		
25 minutes						Gas		
30 minutes						Gas & Water		
						Water		

Steady Flow

Surges

Down to Nothing

Nothing

Gas

Gas & Water

Water

**If bradenhead flowed water, check all of the descriptions that apply below:**

CLEAR \_\_\_\_\_ FRESH \_\_\_\_\_ SALTY \_\_\_\_\_ SULFUR \_\_\_\_\_ BLACK \_\_\_\_\_

5 MINUTE SHUT-IN BRADENHEAD 8 INTERMEDIATE \_\_\_\_\_

REMARKS:

By

Bill Wilson

Witness

Switcher

(Position)