NEW MEXICO ENERGY, MINERALS & NATURAL RESOURCES DEPARTMENT

Oil Conservation Division
Aztec District Office
1000 Rio Brazos Road
Aztec, NM 87410
(505)334-6178 FAX:(505)334-6170

http://emnrd.state.nm.us/ocd/District III/3distric.htm

BRADENHEAD TEST REPORT

(Submit 1 copy to above address)

RCVD MAY18'07

ATIL CONS. DIV. DIST. 3 **Date of Test** 3-9-07 Operator Dugan Production Corp. API# 30-039-20194 5 Location: Unit D Section 20 Township 25N Range 7W Nordhaus Well No. **Property Name** Casing 100 Well Status(Shut-In of Producing) Initial PSI: Tubing Intermediate Bradenhead -OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH PRESSURE Bradenhead **FLOW CHARACTERISTICS** Interm TIME ВΗ Int Csg Int Csg **BRADENHEAD** INTERMEDIATE 100 5 mintues Steady Flow 10 minutes 100 Surges 100 15 minutes Down to Nothing 20 minutes Nothing 25 minutes Gas 30 minutes Gas & Water Water If bradenhead flowed water, check all of the descriptions that apply below: FRESH SALTY SULFUR BLACK **5 MINUTE SHUT-IN BRADENHEAD** INTERMEDIATE REMARKS: Bill Wilson Ву Witness

> Switcher (Position)