NEW MEXICO ENERGY, MINERALS & NATURAL RESOURCES DEPARTMENT

Oil Conservation Division Aztec District Office 1000 Rio Brazos Road Aztec, NM 87410

(505)334-6178 FAX:(505)334-6170

http://emnrd.state.nm.us/ocd/District III/3distric.htm

BRADENHEAD TEST REPORT

(Submit 1 copy to above address)

RCVD MAY18'07 OIL CONS. DIV.

DIST. 3 3-9-07 Operator Dugan Production Corp. API# 30-039-20197 Date of Test Well No. 8 Location: Unit I Section 20 Township 25N Range 7W Property Name Nordhaus Well Status(Shut-In or(Producing)) Initial PSI: Tubing 90 Intermediate Casing 90 Bradenhead OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH **PRESSURE FLOW CHARACTERISTICS** Bradenhead Interm Int Csg TIME Int **BRADENHEAD** INTERMEDIATE Csg 90 5 mintues Steady Flow 10 minutes Surges 90 15 minutes **Down to Nothing** 20 minutes (Nothing) 25 minutes Gas 30 minutes Gas & Water Water If bradenhead flowed water, check all of the descriptions that apply below: SALTY CLEAR FRESH SULFUR BLACK **5 MINUTE SHUT-IN BRADENHEAD** INTERMEDIATE REMARKS: Bill Wilson Ву Witness

> Switcher (Position)