

NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

Oil Conservation Division
Aztec District Office
1000 Rio Brazos Road
Aztec, NM 87410
(505)334-6178 FAX:(505)334-6170

<http://emnr.state.nm.us/ocd/District/III/3district.htm>

BRADENHEAD TEST REPORT
(Submit 1 copy to above address)

RCVD MAY 18 07

OIL CONS. DIV.

DIST. 3

Date of Test 5-9-07 Operator Dugan Production Corp. API # 30-039-25739
Property Name Mona Lisa Well No 1 Location: Unit P Section 14 Township 26N Range 7W
Well Status(Shut-In or Producing) Initial PSI: Tubing 30 Intermediate N/A Casing 60 Bradenhead 10

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

PRESSURE

TIME	Bradenhead			Interm	
	BH	Int	Csg	Int	Csg
5 minutes	<u>0</u>		<u>60</u>		
10 minutes	<u>0</u>		<u>60</u>		
15 minutes	<u>0</u>		<u>60</u>		
20 minutes					
25 minutes					
30 minutes					

Steady Flow

Surges

Down to Nothing

Nothing

Gas

Gas & Water

Water

FLOW CHARACTERISTICS

BRADENHEAD	INTERMEDIATE

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN BRADENHEAD 0 INTERMEDIATE _____

REMARKS:

By

Bill Wilson

Witness

Switcher

(Position)