

NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

Oil Conservation Division
Aztec District Office
1000 Rio Brazos Road
Aztec, NM 87410
(505)334-6178 FAX:(505)334-6170

<http://emnr.state.nm.us/ocd/District/III/3district.htm>

BRADENHEAD TEST REPORT

(Submit 1 copy to above address)

RCVD MAY18'07
OIL CONS. DIV.

DIST. 3

Date of Test 5-9-07 Operator Dugan Production Corp. API # 30-039-25745
Property Name Mona Lisa Well No. 2 Location: Unit J Section 14 Township 26N Range 7W
Well Status(Shut-In or Producing) Initial PSI: Tubing 50 Intermediate N/A Casing 80 Bradenhead 5

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

PRESSURE

TIME	Bradenhead			Interm		
	BH	Int	Csg	Int	Csg	
5 minutes	<u>0</u>		<u>80</u>			
10 minutes	<u>0</u>		<u>80</u>			
15 minutes	<u>0</u>		<u>80</u>			
20 minutes						
25 minutes						
30 minutes						

Steady Flow

Surges

Down to Nothing

Nothing

Gas

Gas & Water

Water

FLOW CHARACTERISTICS

BRADENHEAD	INTERMEDIATE

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN BRADENHEAD 0 INTERMEDIATE _____

REMARKS:

By Bill Wilson
Switcher
(Position)

Witness _____