

NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

Oil Conservation Division
Aztec District Office
1000 Rio Brazos Road
Aztec, NM 87410
(505)334-6178 FAX:(505)334-6170

<http://emnr.state.nm.us/ocd/District/III/3district.htm>

BRADENHEAD TEST REPORT
(Submit 1 copy to above address)

RCVD MAY25'07
OIL CONS. DIV.

DIST. 3

Date of Test 5-15-07 Operator Dugan Production Corp. API # 30-039-05695
Property Name Kilgore Well No. 1 Location: Unit P Section 36 Township 25N Range 2W
Well Status(Shut-In or Producing) Initial PSI: Tubing 110# Intermediate Casing 105.5# Bradenhead 0#

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

PRESSURE

TIME	Bradenhead			Interm		
	BH	Int	Csg	Int	Csg	
5 minutes	0		105.5			
10 minutes	0		106			
15 minutes			106			
20 minutes	0		107.3			
25 minutes						
30 minutes						

FLOW CHARACTERISTICS

BRADENHEAD	INTERMEDIATE
X	

Steady Flow
Surges
Down to Nothing
Nothing
Gas
Gas & Water
Water

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR FRESH SALTY SULFUR BLACK

5 MINUTE SHUT-IN

BRADENHEAD

0#

INTERMEDIATE

REMARKS:

By

Carl J. Meeks

Witness

Switcher

(Position)