

NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

Oil Conservation Division
Aztec District Office
1000 Rio Brazos Road
Aztec, NM 87410
(505)334-6178 FAX:(505)334-6170

[http://emnr.state.nm.us/ocd/District III/3district.htm](http://emnr.state.nm.us/ocd/District%20III/3district.htm)

BRADENHEAD TEST REPORT

(Submit 1 copy to above address)

RCVD MAY25'07
OIL CONS. DIV.
DIST. 3

Date of Test 5-21-07 Operator Dugan Production Corp. API # 30-039-06000
Property Name Hurt Well No. 4 Location: Unit J Section 14 Township 25N Range 3W
Well Status(Shut-In or Producing) Initial PSI: Tubing 23 Intermediate — Casing 0 # Bradenhead 0 #

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

PRESSURE

TIME	Bradenhead			Interm		
	BH	Int	Csg	Int	Csg	
5 minutes	0		0			
10 minutes	0		0			
15 minutes	0		0			
20 minutes	0		0			
25 minutes						
30 minutes						

Steady Flow

Surges

Down to Nothing

Nothing

Gas

Gas & Water

Water

FLOW CHARACTERISTICS

BRADENHEAD

INTERMEDIATE

BRADENHEAD	INTERMEDIATE

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN

BRADENHEAD

0

INTERMEDIATE

REMARKS:

By

Carl J. Meek

Witness

Switcher

(Position)