NEW MEXICO ENERGY, MINERALS & NATURAL RESOURCES DEPARTMENT

Oil Conservation Division
Aztec District Office
1000 Rio Brazos Road
Aztec, NM 87410

(505)334-6178 FAX:(505)334-6170

http://emnrd.state.np.us/ocd/District Ill/3distric htm

BRADENHEAD TEST REPORT (Submit 1 copy to above address)

OIL CONS. DIV.

DIST. 3

										יוכנט.	J	
Date of Test	5.9.0	7 Oper	ator <u>Duga</u>	n Productio	on Corp.	API#	30-039)39-22494			-	
Property Name					_Location: U					24N	Range	2W
Well Status(Shut-In or Producing) Initial PSI:			al PSI: Tubing	90#	/ Intermediate	•	Casing	18	-v#_	Bradeni	nead ∂	}
ODEN DDAI	DENUEAD	AND INT		. TO ATM	NODUEDE II	NDN #DLIAL		45.1	UNULTED I	EAOU.		
OPEN BRAI		AND IN I	ERMEDIATE	OAIMC)SPHERE II	NDIVIDUAL	LY FOR	15 N	INUIES	EACH		
	Bradenhead		n			FLOW	CHARACT	reris	TICS			
TIME	BH Int (Csg				ENHEAD		INTERME	DIATE		
5 mintues	0	181		Steady Flov							•	
10 minutes		181		Surges	_						•	
15 minutes	0	181		Down to No							•	
20 minutes		181									•	
		101		Nothing	_						-	
25 minutes		- 		Gas	_							
30 minutes				Gas & Wate	er		i i					
				Water	_						•	
If bradenh	ead flowe	ed water	, check all	of the de	scriptions	that appl	v below	<i>i</i> :				
			,		<u></u>		<u>,</u>	<u>-</u>				
	CL	EAR	FRESH	i	_SALTY _	SULFU	IR	BLAC	K	_		
				<i>*</i>								
5 MINUTE S	SHUT-IN	BRA	DENHEAD		_ IN	TERMEDIATE			-			
REMARKS:												
	<u> </u>	<u></u>	_				.					
				<u>-</u>								
									·····		•	
0	and	()	200 /20			P4						
Ву	_CWY	<u>~///</u>			- w	itness						
		(Posi	cher		_							