

NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

Oil Conservation Division
Aztec District Office
1000 Rio Brazos Road
Aztec, NM 87410
(505)334-6178 FAX:(505)334-6170

<http://emnr.d.state.nm.us/ocd/DistrictIII/3district.htm>

BRADENHEAD TEST REPORT

(Submit 1 copy to above address)

Date of Test 5-23-07 Operator Dugan Production Corp API # 30-043-20318
Property Name Dome Rusty 30-22-6 Well No. 1 Location: Unit B Section 30 Township 22N Range 6W
Well Status(Shut-In or Producing) Initial PSI: Tubing 20 Intermediate 0 Casing 140 Bradenhead 2

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

PRESSURE

TIME	Bradenhead			Interm		
	BH	Int	Csg	Int	Csg	
5 minutes	<u>0</u>		<u>140</u>			
10 minutes	<u>0</u>		<u>140</u>			
15 minutes	<u>0</u>		<u>140</u>			
20 minutes						
25 minutes						
30 minutes						

Steady Flow

Surges

Down to Nothing

Nothing

Gas

Gas & Water

Water

FLOW CHARACTERISTICS

BRADENHEAD

INTERMEDIATE

BRADENHEAD	INTERMEDIATE

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN

BRADENHEAD

0

INTERMEDIATE

REMARKS:

RCVD JUN1'07

OIL CONS. DIV.

DIST. 3

By

Blair

Witness

Switcher

(Position)