

NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

Oil Conservation Division
Aztec District Office
1000 Rio Brazos Road
Aztec, NM 87410
(505)334-6178 FAX:(505)334-6170

[http://emrds.state.nm.us/ocd/District III/3adistrict.htm](http://emrds.state.nm.us/ocd/District%20III/3adistrict.htm)

BRADENHEAD TEST REPORT

(Submit 1 copy to above address)

Date of Test 5-23-07 Operator Dugan Production Corp API # 30-043-20481
Property Name Dome Federal 18-22-6 Well No. 3 Location: Unit 2 Section 18 Township 22N Range 6W
Well Status(Shut-In or Producing) Initial PSI: Tubing 0 Intermediate 0 Casing 30 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

PRESSURE

TIME	Bradenhead			Interm		
	BH	Int	Csg	Int	Csg	
5 minutes	0		30			
10 minutes	0		30			
15 minutes	0		30			
20 minutes						
25 minutes						
30 minutes						

FLOW CHARACTERISTICS

Steady Flow
Surges
Down to Nothing
Nothing
Gas
Gas & Water
Water

BRADENHEAD	INTERMEDIATE

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN BRADENHEAD _____ INTERMEDIATE _____

REMARKS:

RCVD JUN1'07

OIL CONS. DIV.

DIST. 3

By Bolivi
Switcher
(Position)

Witness _____