NEW MEXICO ENERGY, MINERALS & NATURAL RESOURCES DEPARTMENT

Oil Conservation Division
Aztec District Office
1000 Rio Brazos Road
Aztec, NM 87410
(505)334-6178 FAX:(505)334-6170

http://emnrd.state.nm.us/ocd/District III/3distric.htm

BRADENHEAD TEST REPORT

(Submit 1 copy to above address)

Date of Test 5.22-07 Operator	Dugan Production Corp	API# 30-043-20483
Property Name Dome Federal 29-22-6		
Well Status(Shut-In or Producing) Initial PSI:	<u> </u>	
	EDIATE TO ATMOSPHERE INDIV	IVIDUALLY FOR 15 MINUTES EACH
PRESSURE		EL OWLOUAD ACTEDIOTICS
Bradenhead Interm TIME BH Int Csg Int Csg		FLOW CHARACTERISTICS BRADENHEAD INTERMEDIATE
1 (5		BRADENNEAD INTERMEDIATE
0 15	Steady Flow	
	Surges	
15 minutes 0 5	Down to Nothing	
20 minutes	Nothing	
25 minutes	Gas	
30 minutes	Gas & Water	
,	Water	
If bradenhead flowed water, check all of the descriptions that apply below:		
CLEAR	FRESHSALTY	SULFURBLACK
5 MINUTE SHUT-IN BRADENHEAD INTERMEDIATE REMARKS:		
		RCUD JUN1'07
		OIL CONS. DIV.
		DIST. 3
Bolline	Witness	
Switcher		

(Position)