

NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

Oil Conservation Division
Aztec District Office
1000 Rio Brazos Road
Aztec, NM 87410
(505)334-6178 FAX:(505)334-6170

<http://emrds.state.nm.us/ocd/District/III/3distnc.htm>

BRADENHEAD TEST REPORT

(Submit 1 copy to above address)

Date of Test 5-23-07 Operator Dugan Production Corp API # 30-043-20638
Property Name Dome Federal 1-21-7 Well No. 1 - Location: Unit H Section 1 Township 21N Range 7W
Well Status(Shut-In or Producing) Initial PSI: Tubing 3D Intermediate 0 Casing 7D Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

PRESSURE

TIME	Bradenhead			Interm		
	BH	Int	Csg	Int	Csg	
5 minutes	0		7D			
10 minutes	0		7D			
15 minutes	0		7D			
20 minutes						
25 minutes						
30 minutes						

Steady Flow

Surges

Down to Nothing

Nothing

Gas

Gas & Water

Water

FLOW CHARACTERISTICS

BRADENHEAD

INTERMEDIATE

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN

BRADENHEAD

INTERMEDIATE

REMARKS:

RCVD JUN1'07

OIL CONS. DIV.

DIST. 3

By Bellini Switcher
(Position)

Witness _____