

NEW MEXICO ENERGY, MINERALS  
& NATURAL RESOURCES DEPARTMENT

Oil Conservation Division  
Aztec District Office  
1000 Rio Brazos Road  
Aztec, NM 87410  
(505)334-6178 FAX:(505)334-6170

<http://emnr.state.nm.us/ocd/District/III/3district.htm>

**BRADENHEAD TEST REPORT**

(Submit 1 copy to above address)

Date of Test 5-22-7 Operator Dugan Production Corp API # 30-043-20363  
Property Name ~~Summit~~ Federal 26-22-7 Well No. 1 Location: Unit A Section 26 Township 22N Range 7W  
Well Status(Shut-In or Producing) Initial PSI: Tubing 40 Intermediate 0 Casing NA Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

PRESSURE

TIME	Bradenhead			Interm		
	BH	Int	Csg	Int	Csg	
5 minutes	<u>0</u>		<u>NA</u>			
10 minutes	<u>0</u>		<u>NA</u>			
15 minutes	<u>0</u>		<u>NA</u>			
20 minutes						
25 minutes						
30 minutes						

Steady Flow

Surges

Down to Nothing

Nothing

Gas

Gas & Water

Water

FLOW CHARACTERISTICS

BRADENHEAD INTERMEDIATE

BRADENHEAD	INTERMEDIATE

**If bradenhead flowed water, check all of the descriptions that apply below:**

CLEAR \_\_\_\_\_ FRESH \_\_\_\_\_ SALTY \_\_\_\_\_ SULFUR \_\_\_\_\_ BLACK \_\_\_\_\_

5 MINUTE SHUT-IN BRADENHEAD 0 INTERMEDIATE \_\_\_\_\_

REMARKS:

RCVD JUN1'07

OIL CONS. DIV.

DIST. 3

By Bdure  
Switcher  
(Position)

Witness \_\_\_\_\_