

NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

Oil Conservation Division
Aztec District Office
1000 Rio Brazos Road
Aztec, NM 87410
(505)334-6178 FAX:(505)334-6170

<http://emprd.state.nm.us/ocd/District.III/3district.htm>

BRADENHEAD TEST REPORT

(Submit 1 copy to above address)

Date of Test 5-21-07 Operator Dugan Production Corp API # 30-043-20480
Property Name Dome Navajo 17-22-07 Well No. 2 Location: Unit K Section 17 Township 22N Range 7W
Well Status(Shut-In or Producing) Initial PSI: Tubing 0 Intermediate 0 Casing B2 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

TIME	PRESSURE						FLOW CHARACTERISTICS	
	Bradenhead			Interm			BRADENHEAD	INTERMEDIATE
	BH	Int	Csg	Int	Csg			
5 minutes	<u>0</u>		<u>32</u>			Steady Flow		
10 minutes	<u>0</u>		<u>32</u>			Surges		
15 minutes	<u>0</u>		<u>32</u>			Down to Nothing		
20 minutes						<u>Nothing</u>		
25 minutes						Gas		
30 minutes						Gas & Water		
						Water		

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN BRADENHEAD 0 INTERMEDIATE _____

REMARKS:

Changed Bradenhead valve

RCVD JUN1'07
OIL CONS. DIV.

DIST. 3

By Balvie
Switcher
(Position)

Witness _____