

NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

Oil Conservation Division
Aztec District Office
1000 Rio Brazos Road
Aztec, NM 87410
(505)334-6178 FAX:(505)334-6170

[http://emnr.state.nm.us/ocd/District III/3district.htm](http://emnr.state.nm.us/ocd/District%20III/3district.htm)

BRADENHEAD TEST REPORT

(Submit 1 copy to above address)

Date of Test 5-25-07 Operator Dugan Production Corp API # 30-043-20988
Property Name Rusty Nail Corn Well No. 90 Location: Unit C Section 34 Township 22N Range 6W
Well Status(Shut-In or Producing) Initial PSI: Tubing Ø Intermediate Ø Casing 60 Bradenhead Ø

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

TIME	PRESSURE						FLOW CHARACTERISTICS		
	Bradenhead			Interm			BRADENHEAD	INTERMEDIATE	
	BH	Int	Csg	Int	Csg				
5 minutes	<u>Ø</u>		<u>60</u>					Steady Flow	
10 minutes	<u>Ø</u>		<u>60</u>					Surges	
15 minutes	<u>Ø</u>		<u>60</u>					Down to Nothing	
20 minutes								<u>Nothing</u>	
25 minutes								Gas	
30 minutes								Gas & Water	
								Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN BRADENHEAD Ø INTERMEDIATE _____

REMARKS:

RCVD JUN1'07

OIL CONS. DIV.

DIST. 3

By Ballie
Switcher
(Position)

Witness _____