•	•			
In Lieu of UNITED STATES Form 3160 DEPARTMENT OF INTERIOR (June 1990) BUREAU OF LAND MANAGEME		ENT OF INTERIOR	FORM APPROVED Budget Bureau No. 1004-0135 Expires: March 33, 1993	
SUNDRY NOTICE AND REPORTS ON WELLS Do not use this form for proposals to drill or to deepen or reentry to a different reservoir. Use "APPLICATION TO DRILL" for permit for such proposals				ase Designation and Serial No. /
			6. If Indian, Allottek or Aribe Name (5)	
SUBMIT IN TRIPLICATE			7. If	Unit or CA, Agreement Designation 1/49
1.	Type of Well Oil Well X Gas Well Other			ell Name and No. DSA UNIT #138C
2.	Name of Operator WILLIAMS PRODUCTION COMPANY			PI Well No. -045-34212
3.	Address and Telephone No. PO BOX 3102 MS 25-2, TULSA, OK 74101 (918) 573-6254			eld and Pool, or Exploratory Area ANCO MESAVERDE
4.	4. Location of Well (Footage, Sec., T., R., M., or Survey Description) 2265' FNL & 910' FEL, SE/4 NE/4 SEC 17-T31N-R06W			ounty or Parish, State NN JUAN, NM
CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA				
	TYPE OF SUBMISSION TYPE OF ACTION			
•	Notice of Intent Abandonment Recompletion X Subsequent Report Plugging Back		Change of Plans New Construction Non-Routine Fracturing	
	Final Abandonment Casing Repair Altering Casing Other Set surface csg		Water Shut-Off Conversion to Injection Dispose Water	
			(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)	
Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*				
05-26-2007 Rotary drl 12 1/2" hole section from 0' to 370', TD surface hole @ 0100 hrs, 5/26/07. POOH std back 6 1/2" DC's in derrick. RU casers, run 8 jts 9 5/8", 36#, K-55 csg, landed @ 330' on 5/26/07 @ 0600 hrs. RU cementers.				
05-27-2007 Cmt 9 5/8" csg @ 330', shoe depth, single slurry cmt job, 10 bbls FW spacer, 250 sxs (353 cu.ft.) Type III cmt + 2% CaCl-2 + .25#/sx Cello Flake + 20.87 bbl water = 40.13 bbls. Displace w/ 24 bbl water. Bump plug from 75 to 120 psi, PD @ 03:00 hrs. Check float, held OK. 44 bbls cmt returns to surface, TOC on surface csg @ surface. WOC, back out 9 5/8" landing jt, make up 9 5/8" 24" nipple & WH, nipple up BOP. Test BOP & related equip, low test to 250 psi for 5 min, high test to 2000 psi for 10 min, 9 5/8" csg to 2000 psi for 30 min, all tests good. MU 8 3/4" bit, TIH & tag up @ 290'. Kelly up & drl cmt, insert float, cmt & shoe jt from 290' to 330'. CO from 330' to				
370'. Rotary drl 8 ¾" hole section from 370' to 400'. Circ to cond mud & TOOH to LD 6 ½" DC's. RCVD JUN5'07 ACCEPTED FOR RECOLD				
OIL CONS. DIV. JUN 6 4 2007 DIST. 3				

I hereby certify that the foregoing is true and correct

Signed Ross Title Sr. Production Analyst Date May 30, 2007.

(This space for Federal or State office use)

Approved by Title Date Date Conditions of approval, if any:

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent

statements or representations as to any matter within its jurisdiction.