

RECEIVED

Scorpion Drilling Company
PO Box 1951
Farmington New Mexico 87499
scorpiondrilling@advantas.net
AP (505) 326-5601
Fax (505) 325-1786

JUN 12 2007
MCELVAIN OIL & GAS
PROPERTIES INC

February 6, 2007

Reference:

McElvain Oil & Gas Properties, Inc.
Wiedemer #6
Sec. 34, T27N, R10W
San Juan County, New Mexico
API No. 30-045-34059

A total of five (5) deviation surveys were run using a SURE SHOT tool. These surveys were as follows:

Surface Hole – 214' at $\frac{3}{4}$

Production Hole – 800' = $\frac{1}{2}$, 1330' = 1, 1922' = $1 \frac{1}{4}$ and 2508' = 1


These surveys were given to McElvain Oil & Gas Properties, Inc. for placement in the well file.

This is correct and accurate to the best of my knowledge.

Henry Valdez




President / General Manager
Scorpion Drilling Company



Notary Public

My Commission Expires February 24, 2010



RCVD JUN11'07
OIL CONS. DIV.
DIST. 3

— Used C104 for Directional Survey —

Physical Address – 1313 W. Murray Drive, Farmington New Mexico, 87401
Henry Valdez (505) 320-5740

Vic Morrow (505) 320-6922