



NEW MEXICO ENERGY, MINERALS
and
NATURAL RESOURCES
DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178
FAX: (505) 334-6170
[www.emnrd.state.nm.us/ocd/District 3/district3.htm](http://www.emnrd.state.nm.us/ocd/District%203/district3.htm)

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

Date of Test: 5-24-07 Operator: Merrion Oil & Gas Corporation API # 30-039-23057

Property Name: Canada Mesa Well No. 4E Location: Unit F Section 10 Township 24N Range 6W

Well Status (Shut-In or Producing) Tubing 80 Intermediate Casing 120 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

TIME	PRESSURES:			BRADENHEAD FLOWED	INTERMEDIATE FLOWED
	BRADENHEAD	INTERMEDIATE	CASING		
5 minutes	<u>0</u>			Steady Flow	
10 minutes	<u>0</u>			Surges	
15 minutes	<u>0</u>			Down to Nothing	
20 minutes				Nothing <u>✓</u>	
25 minutes				Gas	
30 minutes				Gas & Water	
				Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR FRESH SALTY SULFUR BLACK

5 MINUTE SHUT-IN BRADENHEAD 0 INTERMEDIATE

RCVD JUN8'07
OIL CONS. DIV.
DIST. 3

REMARKS:

vulnerable area

By Frank Hancock

Witness

(Position)

pumper

E-mail address