

## NEW MEXICO ENERGY, MINERALS and NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION AZTEC DISTRICT OFFICE 1000 RIO BRAZOS ROAD AZTEC NM 87410 (505) 334-6178

FAX: (505) 334-6170 www.emnrd.state.nm.us/ocd/District 3/district3.htm

## BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

Date of Test: <u>5 25 - 0</u> 7 Operator: _	Merrion Oil & Gas API #: 30-039	<u>-27563</u>
Property Name: <u>Blueberry Buckle</u> Well No.: <u>Com 2</u>	2 Location: Unit: Section: 32 Township: 3	0N Range: 7W
Well Status (Shut-In or Producing) Tubing 40	Intermediate Casing 95 Bradenl	nead
OPEN BRADENHEAD AND INTERMEDIATE	TO ATMOSPHERE INDIVIDUALLY FOR	15 MINUTES EACH
PRESSURES: TIME BRADENHEAD INTERMEDIATE CASING	BRADENHEAD FLOWED	INTERMEDIATE FLOWED
5 minutes O	Steady Flow	
10 minutes O	Surges	
15 minutes	Down to Nothing	
20 minutes	Nothing	
25 minutes	Gas_ L	.,
30 minutes	Gas & Water	
	Water	
If bradenhead flowed water, check all of the description	as the top of the top	RCVD JUN8'07
CLEAR FRESH SALTY	SULFURBLACK	DIL CONS. DIV. DIST. 3
5 MINUTE SHUT-IN BRADENHEAD <u>O</u>	INTERMEDIATE	
REMARKS:		
		79-61
By Frank Hause	Witness	
By Frank Hausens		
E-mail address		