

Submit 3 Copies To Appropriate District
Office
District I
1625 N. French Dr., Hobbs, NM 87240
District II
811 South First, Artesia, NM 87210
District III
1000 Rio Brazos Rd., Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-103
Revised March 25, 1999

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)		WELL API NO. <u>30-039-27481</u>
1. Type of Well: Oil Well <input type="checkbox"/> Gas Well <input checked="" type="checkbox"/> Other		5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
2. Name of Operator <u>ConocoPhillips Company</u> <u>217817</u>		6. State Oil & Gas Lease No. <u>E-347-41</u>
3. Address of Operator <u>5525 Highway 64, NBU 3004, Farmington, NM 87401</u>		7. Lease Name or Unit Agreement Name: <u>San Juan 31-6 Unit</u> <u>31328</u>
4. Well Location Unit Letter <u>P</u> : <u>870</u> feet from the <u>South</u> line and <u>1115</u> feet from the <u>East</u> line Section <u>2</u> Township <u>30N</u> Range <u>6W</u> NMPM County <u>Rio Arriba</u>		8. Well No. <u>SJ 31-6 Unit #210A</u>
10. Elevation (Show whether DR, RKB, RT, GR, etc.) <u>6392' GL</u>		9. Pool name or Wildcat <u>Basin Fruitland Coal</u> <u>71629</u>

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐ MULTIPLE COMPLETION ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☒ PLUG AND ABANDONMENT ☐
CASING TEST AND CEMENT JOB ☐

OTHER: ☐ OTHER: Spud Report ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

9/17/03 MIRU Key #49. Spud 12-1/4" hole @ 2030 hrs 9/17/03. Drilled to 227'. Circ. hole. RIH w/9-5/8", 32.3# H-40 casing and set @ 220'. RU Schlumberger to cement. Pumped a preflush of 20 bbls FW w/dye in last 10 bbls. Pumped 150 sx (174 cf - 31 bbl slurry) Class G cement w/2% CaCl₂ & 1/4#/sx Cello-flake. Released wiper plug and displaced w/15.3 bbls FW. Bumped plug w/400 psi @ 0521 hrs 9/18/03. Circ. 73 sx good cement to surface. RD Schlumberger. WOC. NU WH & BOP. PT BOP-OK. PT casing @ 510 psi for 3 minutes and 1100 psi for 30 mintu4s. Good test.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Patsy Clugston TITLE SHEAR Administrative Assistant DATE 9/19/03

Type or print name Patsy Clugston Telephone No. 505-599-3454

(This space for State use)

APPROVED BY Charles R DEPUTY OIL & GAS INSPECTOR, DIST. 22 DATE SEP 22 2003

Conditions of approval, if any: