



(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office Santa Fe

Lease No. 047017-B

Unit SE/4 Sec. 24, T-28N
R-11W, N.M.P.M. San Juan
County, New Mexico

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL.....	SUBSEQUENT REPORT OF WATER SHUT-OFF.....
NOTICE OF INTENTION TO CHANGE PLANS.....	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.....
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....	SUBSEQUENT REPORT OF ALTERING CASING.....
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.....	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR.....
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....	SUBSEQUENT REPORT OF ABANDONMENT.....
NOTICE OF INTENTION TO PULL OR ALTER CASING.....	SUPPLEMENTARY WELL HISTORY.....
NOTICE OF INTENTION TO ABANDON WELL.....	

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

November 28, 1961

Angel Peak
Well No. 10-B is located 1940 ft. from N line and 1980 ft. from E line of sec. 24
SE/4 Sec. 24 (1/4 Sec. and Sec. No.) 28-N 11-W N.M.P.M.
(Twp.) (Range) (Meridian)
Fulcher-Kutz San Juan County New Mexico
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is 5859 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Set 10 sacks cement plug in 5 1/2" casing and open hole at 1849'.
Shot casing off at 1514'. Pulled 1514' of casing. Filled hole with mud.
Set 30 sacks cement plug inside stub and open hole from 1490 to 1530. Set
10 sacks cement plug in surface. Set 6 sacks plug with regulation marker.
Cleaned location.



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company ANGEL PEAK OIL COMPANY

Address P. O. Box 808

Farmington, New Mexico

By L. S. Muennink

Title Production Superintendent