

NEW MEXICO ENERGY, MINERALS  
& NATURAL RESOURCES DEPARTMENT

Oil Conservation Division  
Aztec District Office  
1000 Rio Brazos Road  
Aztec, NM 87410  
(505)334-6178 FAX (505)334-6170


<http://emnr.state.nm.us/ocd/District/III/3district.htm>

**BRADENHEAD TEST REPORT**

(Submit 1 copy to above address)

Date of Test 6-12-07 Operator Dugan Production Corp API # 30-039-05657  
Property Name Jicarilla Well No 1 Location. Unit A Section 3 Township 24N Range 4W  
Well Status(Shut-In or Producing) Initial PSI: Tubing 51 Intermediate      Casing 156 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

TIME	PRESSURE						FLOW CHARACTERISTICS	
	Bradenhead			Interm			BRADENHEAD	INTERMEDIATE
	BH	Int	Csg	Int	Csg			
5 minutes								
10 minutes								
15 minutes								
20 minutes								
25 minutes								
30 minutes								

Steady Flow  
Surges  
Down to Nothing  
Nothing  
Gas  
Gas & Water  
Water

**If bradenhead flowed water, check all of the descriptions that apply below:**

CLEAR      FRESH      SALTY      SULFUR      BLACK     

**5 MINUTE SHUT-IN** BRADENHEAD      INTERMEDIATE     

REMARKS

No pressure.

By

A. J. Valdez

Witness

Switcher

(Position)