

NEW MEXICO ENERGY, MINERALS  
& NATURAL RESOURCES DEPARTMENT

Oil Conservation Division  
Aztec District Office  
1000 Rio Brazos Road  
Aztec, NM 87410  
(505)334-6178 FAX:(505)334-6170

<http://emnr.state.nm.us/ocd/District/III/3distric.htm>


**BRADENHEAD TEST REPORT**

(Submit 1 copy to above address)

Date of Test 6-13-07 Operator Dugan Production Corp API # 30-039-21978  
Property Name Jicarilla Otero Com Well No 1 Location Unit M Section 22 Township 24N Range 5W  
Well Status(Shut-In or Producing) Initial PSI: Tubing 50 Intermediate 50 Casing 50 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

TIME	PRESSURE							FLOW CHARACTERISTICS	
	Bradenhead			Interm				BRADENHEAD	INTERMEDIATE
	BH	Int	Csg	Int	Csg				
5 minutes							Steady Flow		
10 minutes							Surges		
15 minutes							Down to Nothing		
20 minutes							<u>Nothing</u>		
25 minutes							Gas		
30 minutes							Gas & Water		
							Water		



**If bradenhead flowed water, check all of the descriptions that apply below:**

CLEAR \_\_\_\_\_ FRESH \_\_\_\_\_ SALTY \_\_\_\_\_ SULFUR \_\_\_\_\_ BLACK \_\_\_\_\_

**5 MINUTE SHUT-IN** BRADENHEAD \_\_\_\_\_ INTERMEDIATE \_\_\_\_\_

REMARKS:

No Pressure

By [Signature]  
Switcher  
(Position)

Witness \_\_\_\_\_