

NEW MEXICO ENERGY, MINERALS  
& NATURAL RESOURCES DEPARTMENT

Oil Conservation Division  
Aztec District Office  
1000 Rio Brazos Road  
Aztec, NM 87410  
(505)334-6178 FAX:(505)334-6170

[http://emnrd.state.nm.us/ocd/District III/3district.htm](http://emnrd.state.nm.us/ocd/District%20III/3district.htm)

**BRADENHEAD TEST REPORT**

(Submit 1 copy to above address)

Date of Test 6-28-07 Operator Dugan Production Corp API # 30-039-23076  
Property Name Strawberry Well No 1 Location Unit L Section 3 Township 23N Range 6W  
Well Status(Shut-In or Producing) Initial PSI. 85 Intermediate 48 Casing 48 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

PRESSURE

TIME	Bradenhead			Interm		
	BH	Int	Csg	Int	Csg	
5 minutes	0					
10 minutes						
15 minutes						
20 minutes						
25 minutes						
30 minutes						

Steady Flow  
Surges  
Down to Nothing  
Nothing  
Gas  
Gas & Water  
Water

FLOW CHARACTERISTICS

BRADENHEAD INTERMEDIATE

BRADENHEAD	INTERMEDIATE



**If bradenhead flowed water, check all of the descriptions that apply below:**

CLEAR \_\_\_\_\_ FRESH \_\_\_\_\_ SALTY \_\_\_\_\_ SULFUR \_\_\_\_\_ BLACK \_\_\_\_\_

**5 MINUTE SHUT-IN** BRADENHEAD \_\_\_\_\_ INTERMEDIATE \_\_\_\_\_

REMARKS.

No Pressure.  
Pump Jack down hole in tubing.

By [Signature]  
Switcher  
(Position)

Witness \_\_\_\_\_