

NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

Oil Conservation Division
Aztec District Office
1000 Rio Brazos Road
Aztec, NM 87410
(505)334-6178 FAX. (505)334-6170

<http://emnr.state.nm.us/ocd/District/III/3district.htm>

BRADENHEAD TEST REPORT

(Submit 1 copy to above address)

Date of Test 6-14-07 Operator Dugan Production Corp API # 30-039-21097
Property Name Jicarilla 28-3 Well No 1 Location: Unit G Section 6 Township 28N Range 3W
Well Status(Shut-In or Producing) Initial PSI: Tubing 190 Intermediate _____ Casing 520 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

TIME	PRESSURE						FLOW CHARACTERISTICS	
	Bradenhead			Interm			BRADENHEAD	INTERMEDIATE
	BH	Int	Csg	Int	Csg			
5 minutes								Steady Flow Surges Down to Nothing <u>Nothing</u> Gas Gas & Water Water
10 minutes								
15 minutes								
20 minutes								
25 minutes								
30 minutes								



If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN BRADENHEAD _____ INTERMEDIATE _____

REMARKS:

A puff then nothing.

By A. J. Velazquez
Switcher
(Position)

Witness _____