

NEW MEXICO ENERGY, MINERALS  
& NATURAL RESOURCES DEPARTMENT


Oil Conservation Division  
Aztec District Office  
1000 Rio Brazos Road  
Aztec, NM 87410  
(505)334-6178 FAX (505)334-6170

<http://emnr.state.nm.us/ocd/District/III/3district.htm>

**BRADENHEAD TEST REPORT**  
(Submit 1 copy to above address)

Date of Test 10-28-07 Operator Dugan Production Corp API # 30-039-22548  
Property Name South Blanco Navajo 8 Well No 1 Location. Unit A Section 8 Township 23N Range 7W  
Well Status(Shut-In or Producing) Initial PSI: Tubing 51 Intermediate 114 Casing 50 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

TIME	PRESSURE						FLOW CHARACTERISTICS	
	Bradenhead			Interm			BRADENHEAD	INTERMEDIATE
	BH	Int	Csg	Int	Csg			
5 minutes								
10 minutes								
15 minutes								
20 minutes								
25 minutes								
30 minutes								

Steady Flow nothing

Surges

Down to Nothing

Nothing

Gas

Gas & Water

Water


If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR \_\_\_\_\_ FRESH \_\_\_\_\_ SALTY \_\_\_\_\_ SULFUR \_\_\_\_\_ BLACK \_\_\_\_\_

**5 MINUTE SHUT-IN** BRADENHEAD \_\_\_\_\_ INTERMEDIATE \_\_\_\_\_

REMARKS

By



Switcher

(Position)

Witness