Budget	Bureau	Νo.	42-R35	8.4.
Approv	al expire	s 12·	-31-60.	

(,	. en. 1901)						
		G					

(SUBMIT IN TRIPLICATE)

UNITED STATES DEPARTMENT OF THE INTERIOR GEOLOGICAL SURVEY

and O	ffice	·		
			·	
Lease N	O			
Jnit			,	

TT	NDDV	NOTICE	CAND	PEPORTS	ON W	TETT &	
,							
	4		1				
·					***		

		-	F-6 0 10°	
NOTICE OF INTENTION TO	DRILL		SUBSEQUENT REPORT OF WATER SHUT-OFF	
NOTICE OF INTENTION TO	CHANGE PLANS		SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING U.S. GEOLOGICAL SU	JR
NOTICE OF INTENTION TO	TEST WATER SHUT-OFF		SUBSEQUENT REPORT OF ALTERING CASING FARMING ON, NEW M	E.
NOTICE OF INTENTION TO	RE-DRILL OR REPAIR WELL		SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR	
NOTICE OF INTENTION TO	SHOOT OR ACIDIZE		SUBSEQUENT REPORT OF ABANDONMENT.	
NOTICE OF INTENTION TO	PULL OR ALTER CASING		SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO	ABANDON WELL			

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

			·		res	RUMEY 3		1960
	Navajo		in a time .	e Krye e e je				
Well No.	1	is locate	d 330	ft. from $\{N\}$	line and 2	310 ft. from	line of	sec. 18
				[X]			(W)	
NW/4	Sect	lon 18	200	17W				
. C4 E	ec. and Sec. N	o.)	(Twp.)	(Range)		(Meridian)		. :
Wilde	at		Se	n Juan	i e	Nev	Mexico	
173.5.5	(Field)			(County or Subdiv	ision)	(8	ate or Territory)	· ·

The elevation of the derrick floor above sea level is \$228 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

See ettached log report. Well abandoned and plugged March 3, 1957.



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced

Company _	Schule & Brannan Drilling	Co.	· 	
Address	621 Staley Building			
	Wichita Falls, Texas		Bv	Bun & Scholl
	0		Title	Partner