



NEW MEXICO ENERGY, MINERALS
and
NATURAL RESOURCES
DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178
FAX: (505) 334-6170
www.emnrd.state.nm.us/ocd/District 3/district3.htm

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

Date of Test 6/11/07 Operator CDX RIO, LLC API #30-039- 20597
Property Name Jic 151 Well No. 3 Location: Unit 4 Section 4 Township 26 Range 5
Well Status (Shut-In or Producing) Tubing 3 1/2" Intermediate 0 Casing 3 1/2" Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

TIME	PRESSURES:		
	BRADENHEAD	INTERMEDIATE	CASING
5 minutes	<u>0</u>	<u>0</u>	<u>300"</u>
10 minutes	<u>0</u>	<u>0</u>	<u>300"</u>
15 minutes	<u>0</u>	<u>0</u>	<u>300"</u>
20 minutes	<u>END TEST</u>		
25 minutes			
30 minutes			

	BRADENHEAD FLOWED	INTERMEDIATE FLOWED
Steady Flow		
Surges		
Down to Nothing		
Nothing	<u>X</u>	<u>X</u>
Gas		
Gas & Water		
Water		

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN BRADENHEAD 0 INTERMEDIATE 0

REMARKS:

No Pressure in Bradenhead & Intermediate

By Ray Hansen
Field Tech
(Position)

Witness _____

E-mail address _____

