

NEW MEXICO ENERGY, MINERALS and NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178
FAX: (505) 334-6170

www.emnrd.state.nm.us/ocd/District 3/district3.htm

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

	Date of Test 6.8.07 Operator_C	DX RIO, LLC_API #30-039- <u>21643</u>	
OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH PRESSURES: BRADENHEAD INTERMEDIATE 5 minutes 48 Steady Flow 10 minutes 48 Surges 15 minutes Nothing 20 minutes Gas 30 minutes Gas & Water Water Water Water CLEAR FRESH SALTY SULFUR BLACK FREMARKS: REMARKS:	Property Name Jicavi g A Well No. 9	Location: Unit <u>()</u> Section <u>20</u> Township <u>214N</u> Range_5W	
PRESSURES: TIME BRADENHEAD INTERMEDIATE CASING 5 minutes 48	Well Status (Shut-In or Producing) Tubing 48 In	ntermediate Casing 48 Bradenhead Ø	
TIME BRADENHEAD INTERMEDIATE CASING FLOWED 5 minutes	OPEN BRADENHEAD AND INTERMEDIATE TO	ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH	
10 minutes			
Down to Nothing Nothing Sas The bradenhead flowed water, check all of the descriptions that apply below: CLEAR FRESH SALTY SULFUR BLACK SMINUTE SHUT-IN BRADENHEAD INTERMEDIATE REMARKS: Down to Nothing Nothing Received Received	5 minutes 9 48	Steady Flow	
20 minutes	10 minutes 9 48	Surges	
25 minutes Gas	15 minutes Ø 48	Down to Nothing	
Gas & Water	20 minutes	Nothing	
	25 minutes	Gas	
	30 minutes	Gas & Water	
		Water	
	If bradenhead flowed water, check all of the descriptions that apply below:		
	CLEAR FRESH SALTY	SULFUR BLACK	
	OIL CONS. DIV. DIST 3		
	,	INTERMEDIATE	
	REMARKS:		
Pu Ducu a House's are			
Pu A House's are			
Du A) Lacus a House's are			
By TOUR HANTSON Witness	By Duque Harrison	Witness	
Field Tech	Field Tech		
(Position) F-mail address	(Position) E-mail address		