

NEW MEXICO ENERGY, MINERALS and NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178
FAX: (505) 334-6170

www.emnrd.state.nm.us/ocd/District 3/district3.htm

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

Date of Test June 08, 2007 Operator_CDX RIO, LLC_API #30-039-21994						
Property Name Name Location: Unit L Section 12 Township 24N Range 5W						
Well Status (Shut-In or Producing) Tubing 220 Intermediate NA Casing 222 Bradenhead -1#						
OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH						
TIME	BRADENHEAD	PRESSURES: INTERMEDIATE	CASING_	_	BRADENHEAD FLOWED	INTERMEDIATE FLOWED
5 minutes_	0	NA	222#	Steady Flow		
10 minutes_	0	ZVA	222#	Surges		
15 minutes_	0	NA	222#	Down to Nothing_	X	
20 minutes_				Nothing	·	24/520
25 minutes_				Gas	(32)	IECEIVED 6
30 minutes_				Gas & Water	<u>√6,</u> Ł	IECEIVED %
				Water		CONS DIV DIST 0 A.
If bradenhead flowed water, check all of the descriptions that apply below:						
If bradenhead flowed water, check all of the descriptions that apply below: CLEAR FRESH SALTY SULFUR BLACK						
5 MINUTE SHUT-IN BRADENHEAD O INTERMEDIATE						
REMARKS: BH had -1#, bled off to zero upon Opening of 1" ball						
Valve. No action afterwards.						
20	$\mathcal{D} \mathcal{D} \mathcal{N}$	a				
By Dothy K. Watchman Witness NONE						
By Solly R. Watchman Witness NONE PROD. Technician (Position)						
E-mail addres						