

## NEW MEXICO ENERGY, MINERALS and NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION AZTEC DISTRICT OFFICE 1000 RIO BRAZOS ROAD AZTEC NM 87410 (505) 334-6178

FAX: (505) 334-6170 www.emnrd.state.nm.us/ocd/District 3/district3.htm

## **BRADENHEAD TEST REPORT**

(Submit 2 copies to above address)

Date of Test_	6-12	-07	_ Operator_	CDX RIO, LLC_AP	I #30-039- <sub>-</sub>	223	14-
Property Nam	e Jica	villa"E"w	ell No. 2E	Location: Unit $\overline{\mathcal{L}}$	Section_/	<b>⊈</b> Townsh	ip <b>26N</b> Range <u>56</u> 0
Well Status (S	Shut-In or	Producing) T	ubing <i>15</i> 8	Intermediate Car	sing 159	Bradenhe	ead_ <b>Ø</b> _
OPEN BRA	DENHEAI	O AND INTERM	ÆDIATE TO	O ATMOSPHERE INDI	VIDUALL'	Y FOR 15	MINUTES EACH
TIME BRA	DENHEAD	PRESSURES: INTERMEDIAT	E CASING	_	BRADEN FLOWE		INTERMEDIATE FLOWED
5 minutes	Ø		159	_ Steady Flow			
10 minutes	Ø		159	Surges			-
15 minutes	Ø		159	Down to Nothin	ng		
20 minutes				Nothing	X_		
25 minutes				Gas			
30 minutes				Gas & Water		(222	232425262
		•		Water	- 17 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1	SO FIE	CLIVED W
If bradenhead flowed water, check all of the descriptions that apply below:							
Gas & Water							
5 MINUTE SHUT-IN BRADENHEAD INTERMEDIATE INTERMEDIATE							
REMARKS:							
					<del></del>		
				-			
		•					
By Duan	e Tra	eurisou I		Witness	······································		
(Positio	l lec	И					
E-mail address							