



NEW MEXICO ENERGY, MINERALS
and
NATURAL RESOURCES
DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178
FAX: (505) 334-6170
www.emnrd.state.nm.us/ocd/District 3/district3.htm

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

Date of Test 6-7-07 Operator CDX RIO, LLC API #30-039- 22327

Property Name Reames "A" Well No. 1E Location: Unit J Section 24 Township 24N Range 6W

Well Status (Shut-In or Producing) (Producing) Tubing 101 Intermediate Casing 102 Bradenhead 1

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

TIME	PRESSURES:			BRADENHEAD	INTERMEDIATE
	BRADENHEAD	INTERMEDIATE	CASING	FLOWED	FLOWED
5 minutes	<u>Ø</u>		<u>102</u>		
10 minutes	<u>Ø</u>		<u>102</u>		
15 minutes	<u>Ø</u>		<u>102</u>		
20 minutes					
25 minutes					
30 minutes					

Steady Flow

Surges

Down to Nothing X

Nothing

Gas X

Gas & Water


Water

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR FRESH SALTY SULFUR BLACK

5 MINUTE SHUT-IN BRADENHEAD Ø INTERMEDIATE

REMARKS: Blew down in 5 seconds



By Duane Harrison
Field Tech
(Position)

Witness Kelly G. Roberts

E-mail address