



NEW MEXICO ENERGY, MINERALS
and
NATURAL RESOURCES
DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178
FAX: (505) 334-6170

www.emnrd.state.nm.us/ocd/District 3/district3.htm

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

Date of Test 6/5/07 Operator CDX RIO, LLC API #30-039- 22581

Property Name Jicarilla "A" Well No. 2E Location: Unit 0 Section 18 Township 26N Range 5E

Well Status (Shut-In or Producing) Tubing 47 Intermediate Casing 47 Bradenhead Ø

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

TIME	PRESSURES:			BRADENHEAD FLOWED	INTERMEDIATE FLOWED
	BRADENHEAD	INTERMEDIATE	CASING		
5 minutes	<u>Ø</u>		<u>47</u>	Steady Flow <u> </u>	
10 minutes	<u>Ø</u>		<u>47</u>	Surges <u> </u>	
15 minutes	<u>Ø</u>		<u>47</u>	Down to Nothing <u> </u>	
20 minutes				Nothing <u>X</u>	
25 minutes				Gas <u> </u>	
30 minutes				Gas & Water <u> </u>	
				Water <u> </u>	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR FRESH SALTY SULFUR BLACK

5 MINUTE SHUT-IN BRADENHEAD INTERMEDIATE

REMARKS:

By Duane Harrison
Field Tech
(Position)

Witness

E-mail address

