



NEW MEXICO ENERGY, MINERALS
and
NATURAL RESOURCES
DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178
FAX: (505) 334-6170
[www.emnrd.state.nm.us/ocd/District 3/district3.htm](http://www.emnrd.state.nm.us/ocd/District%203/district3.htm)

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

Date of Test 6-8-07 Operator CDX RIO, LLC API #30-039- 22898

Property Name Jicarilla "A" Well No. LE Location: Unit E Section 20 Township 24N Range 7E

Well Status (Shut-In or Producing) Tubing 81 Intermediate — Casing 84 Bradenhead Ø

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH


TIME	PRESSURES:			BRADENHEAD FLOWED	INTERMEDIATE FLOWED
	BRADENHEAD	INTERMEDIATE	CASING		
5 minutes	<u>Ø</u>		<u>84</u>	Steady Flow	
10 minutes	<u>Ø</u>		<u>84</u>	Surges	
15 minutes	<u>Ø</u>		<u>84</u>	Down to Nothing	
20 minutes				Nothing <u>X</u>	
25 minutes				Gas	
30 minutes				Gas & Water	
				Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR — FRESH — SALTY — SULFUR — BLACK —

5 MINUTE SHUT-IN BRADENHEAD Ø INTERMEDIATE —

REMARKS:



By Duane Harrison
Field Tech
(Position)

Witness —

E-mail address —