



NEW MEXICO ENERGY, MINERALS
and
NATURAL RESOURCES
DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178
FAX: (505) 334-6170
www.emnrd.state.nm.us/ocd/District 3/district3.htm

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

Date of Test 6/12/07 Operator CDX RIO, LLC API #30-039- 27839

Property Name JIC 151 Well No. 7 F Location: Unit K Section 4 Township 26 Range 5

Well Status (Shut-In or Producing) Tubing 126th Intermediate N/A Casing 187th Bradenhead Ø

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

TIME	PRESSURES:			BRADENHEAD FLOWED	INTERMEDIATE FLOWED
	BRADENHEAD	INTERMEDIATE	CASING		
5 minutes	<u>Ø</u>		<u>187th</u>	Steady Flow	
10 minutes	<u>Ø</u>		<u>187th</u>	Surges	
15 minutes	<u>Ø</u>		<u>187th</u>	Down to Nothing	
20 minutes	<u>End Test</u>			Nothing <u>X</u>	
25 minutes				Gas	
30 minutes				Gas & Water	
				Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN BRADENHEAD Ø INTERMEDIATE _____

REMARKS:

No pressure being on Bradenhead.

By Ray Dornan
Field Tech
(Position)

Witness _____

E-mail address _____

