



NEW MEXICO ENERGY, MINERALS  
and  
NATURAL RESOURCES  
DEPARTMENT

OIL CONSERVATION DIVISION  
AZTEC DISTRICT OFFICE  
1000 RIO BRAZOS ROAD  
AZTEC NM 87410  
(505) 334-6178  
FAX: (505) 334-6170

www.emnrd.state.nm.us/ocd/District 3/district3.htm

**BRADENHEAD TEST REPORT**

(Submit 2 copies to above address)

Date of Test 6/5/07 Operator CDX RIO, LLC API #30-039- 29204

Property Name Jic-151 Well No. 8F Location: Unit H Section 3 Township 26 Range 5

Well Status (Shut-In or Producing) Tubing 1 1/2 Intermediate N/A Casing 3 1/2 # Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

TIME	PRESSURES:		
	BRADENHEAD	INTERMEDIATE	CASING
5 minutes	<u>0</u>		<u>3 1/2</u>
10 minutes	<u>0</u>		<u>3 1/2</u>
15 minutes	<u>0</u>	<u>Test</u>	<u>3 1/2</u>
20 minutes			
25 minutes			
30 minutes			

BRADENHEAD FLOWED	INTERMEDIATE FLOWED
Steady Flow	
Surges	
Down to Nothing	
Nothing <u>X</u>	
Gas	
Gas & Water	
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR \_\_\_\_\_ FRESH \_\_\_\_\_ SALTY \_\_\_\_\_ SULFUR \_\_\_\_\_ BLACK \_\_\_\_\_

5 MINUTE SHUT-IN BRADENHEAD \_\_\_\_\_ INTERMEDIATE \_\_\_\_\_

REMARKS:

No pressure leak on Bradenhead

By Ray Danner

Witness \_\_\_\_\_

(Position)

E-mail address \_\_\_\_\_

