

"أسل

NEW MEXICO ENERGY, MINERALS and NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178
FAX: (505) 334-6170

www.emnrd.state.nm.us/ocd/District 3/district3.htm

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

Date of Test	6.12.07	Operator_	CDX RIO, LLC_API	#30-039- <u>82</u>	306
Property Name	Jicavilla C" Well	No	Location: Unit <u>M</u> S	Section_13 Towns	hip 220 Range 50
Well Status (Sl	hut-In or Producing) Tub	oing 5 7	Intermediate Cas	ing 146 Bradent	nead <u>B</u>
OPEN BRAD	DENHEAD AND INTERME	DIATE TO	O ATMOSPHERE INDIV	VIDUALLY FOR 15	MINUTES EACH
TIME BRAI	PRESSURES: DENHEAD INTERMEDIATE	CASING	_	BRADENHEAD FLOWED	INTERMEDIATE FLOWED
5 minutes	Ø	146	Steady Flow		
10 minutes	Ø	146	Surges		,
15 minutes	Ø	146	Down to Nothin	g	
20 minutes			Nothing		
25 minutes			Gas		
30 minutes			Gas & Water		232425262
			Water	/(RECEIVED
If bradenhead flowed water, check all of the descriptions that apply below:					
CLEAR_	FRESH SAL	.TY	SULFUR BLACE	\\vert_{\text{i}_2}	OIL CONS. DIV. DIST 3
5 MINUTE SHUT-IN BRADENHEAD 2			INTERMEDIATE		OIL CONS. DIV. DISI 3 CO
REMARKS:					
				<u></u>	
	,				
By Dual	e Hamison	in the same of the	Witness		
Tield (Position	Tech				
E-mail address					