



NEW MEXICO ENERGY, MINERALS
and
NATURAL RESOURCES
DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178
FAX: (505) 334-6170
www.emnrd.state.nm.us/ocd/District 3/district3.htm

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

Date of Test June 08, 2007 Operator CDX RIO, LLC API #30-039- 05995

Property Name Jicarilla Cont Well No. 148 #7 Location: Unit P Section 15 Township 25N Range 5W

Well Status (Shut-In or Producing) Tubing 50[#] Intermediate NA Casing 54[#] Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

TIME	PRESSURES:		
	BRADENHEAD	INTERMEDIATE	CASING
5 minutes	<u>0</u>	<u>NA</u>	<u>54</u> [#]
10 minutes	<u>0</u>	<u>NA</u>	<u>54</u> [#]
15 minutes	<u>0</u>	<u>NA</u>	<u>54</u> [#]
20 minutes			
25 minutes			
30 minutes			

	BRADENHEAD FLOWED	INTERMEDIATE FLOWED
Steady Flow		
Surges		
Down to Nothing		
Nothing	<u>X</u>	
Gas		
Gas & Water		
Water		

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN BRADENHEAD 0 INTERMEDIATE _____

REMARKS:

BH was dug out, opened Valve. No pressure, No Vapor,
No action.

By Bobby R. Hatchman
Prod. Tech.
(Position)

Witness NONE

E-mail address _____

