



NEW MEXICO ENERGY, MINERALS  
and  
NATURAL RESOURCES  
DEPARTMENT

OIL CONSERVATION DIVISION  
AZTEC DISTRICT OFFICE  
1000 RIO BRAZOS ROAD  
AZTEC NM 87410  
(505) 334-6178  
FAX: (505) 334-6170  
www.emnrd.state.nm.us/ocd/District 3/district3.htm

**BRADENHEAD TEST REPORT**

(Submit 2 copies to above address)

Date of Test 6-12-2007 Operator CDX RIO, LLC API #30-039- 20568  
Property Name Jicarilla Cont. 146 Well No. 23 Location: Unit D Section 9 Township 25N Range 5W  
Well Status (Shut-In or Producing) Tubing 116<sup>#</sup> Intermediate N/A Casing 115<sup>#</sup> Bradenhead 0<sup>#</sup>

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

TIME	PRESSURES:			BRADENHEAD	INTERMEDIATE
	BRADENHEAD	INTERMEDIATE	CASING	FLOWED	FLOWED
5 minutes	<u>0</u>		<u>115</u> <sup>#</sup>	Steady Flow	
10 minutes	<u>0</u>		<u>115</u> <sup>#</sup>	Surges	
15 minutes	<u>0</u>		<u>115</u> <sup>#</sup>	Down to Nothing	
20 minutes				Nothing	<u>X</u>
25 minutes				Gas	
30 minutes				Gas & Water	
				Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR \_\_\_\_\_ FRESH \_\_\_\_\_ SALTY \_\_\_\_\_ SULFUR \_\_\_\_\_ BLACK \_\_\_\_\_

5 MINUTE SHUT-IN BRADENHEAD 0<sup>#</sup> INTERMEDIATE \_\_\_\_\_

REMARKS: Bradenhead had no pressure upon opening of 1" valve, or vapor.

By Walt  
Field Technician  
(Position)

Witness NONE

E-mail address \_\_\_\_\_

