



NEW MEXICO ENERGY, MINERALS
and
NATURAL RESOURCES
DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178
FAX: (505) 334-6170
www.emnrd.state.nm.us/ocd/District 3/district3.htm

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

Date of Test 6-11-2007 Operator CDX RIO, LLC API #30-039- 22145

Property Name Jicarilla Cont. 146 Well No. 28 Location: Unit M Section 9 Township 25N Range 5W

Well Status (Shut-In or Producing) Tubing 83# Intermediate N/A Casing 80# Bradenhead 28#

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

TIME	PRESSURES:		
	BRADENHEAD	INTERMEDIATE	CASING
5 minutes	<u>0</u>		<u>81#</u>
10 minutes	<u>0</u>		<u>81#</u>
15 minutes	<u>0</u>		<u>81#</u>
20 minutes	<u>0</u>		<u>81#</u>
25 minutes	<u>0</u>		<u>81#</u>
30 minutes	<u>0</u>		<u>81#</u>

	BRADENHEAD FLOWED	INTERMEDIATE FLOWED
Steady Flow		
Surges		
Down to Nothing	<u>X</u>	
Nothing		
Gas	<u>X</u>	
Gas & Water		
Water		

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN BRADENHEAD 0 INTERMEDIATE _____

REMARKS:

Braden head had very little vapor and bled down to nothing after opening 1" valve.

By WCS

Witness NONE

Field Technician

(Position)

E-mail address _____

