



NEW MEXICO ENERGY, MINERALS
and
NATURAL RESOURCES
DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178
FAX: (505) 334-6170
www.emnrd.state.nm.us/ocd/District 3/district3.htm

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

Date of Test 6-11-2007 Operator CDX RIO, LLC API #30-039- 22480

Property Name Jicarilla Cont. 146 Well No. 29 Location: Unit A Section 9 Township 25N Range 5W

Well Status (Shut-In or Producing) Tubing 55# Intermediate N/A Casing 54# Bradenhead -1#

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

TIME	PRESSURES:			BRADENHEAD	INTERMEDIATE
	BRADENHEAD	INTERMEDIATE	CASING	FLOWED	FLOWED
5 minutes	<u>0</u>		<u>54#</u>		
10 minutes	<u>0</u>		<u>54#</u>		
15 minutes	<u>0</u>		<u>54#</u>		
20 minutes					
25 minutes					
30 minutes					
				Steady Flow	
				Surges	
				Down to Nothing	<u>X</u>
				Nothing	
				Gas	<u>X</u>
				Gas & Water	
				Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN BRADENHEAD 0 INTERMEDIATE _____

REMARKS:

Bradenhead had less than 1# of pressure and bled
down to nothing after 1" valve was opened.

By Went

Witness NONE

Field Technician

(Position)

E-mail address _____

