



NEW MEXICO ENERGY, MINERALS
and
NATURAL RESOURCES
DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178
FAX: (505) 334-6170
www.emnrd.state.nm.us/ocd/District 3/district3.htm

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

Date of Test June 18, 2007 Operator CDX RIO, LLC API # 30-039-23655
Property Name Jicarilla Cont. 148 Well No. #32 Location: Unit D Section 14 Township 25N Range 5W
Well Status (Shut-In or Producing) Tubing 73[#] Intermediate NA Casing 101[#] Bradenhead -1/2[#]

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

TIME	PRESSURES:			BRADENHEAD	INTERMEDIATE
	BRADENHEAD	INTERMEDIATE	CASING	FLOWED	FLOWED
5 minutes	<u>0</u>	<u>NA</u>	<u>101</u> [#]	Steady Flow	
10 minutes	<u>0</u>	<u>NA</u>	<u>100</u> [#]	Surges	
15 minutes	<u>0</u>	<u>NA</u>	<u>100</u> [#]	Down to Nothing	<u>X</u>
20 minutes				Nothing	
25 minutes				Gas	<u>X</u>
30 minutes				Gas & Water	
				Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN BRADENHEAD 0 INTERMEDIATE _____

REMARKS: BH had less than 1/2[#], bled off to zero upon opening of 1" ball valve. No action afterwards. Dug out Main BH Valve, Open.

By Bobby R. Hatchman
PROD. TECH.
(Position)

Witness NONE

E-mail address _____

